



Your Company Name Here
123 Somewhere Street
Anywhere, US 12345
Lice. #1234

Sample Inspection Report



1234 School House Road
Yourtown, US 12345

Table of Contents

Inspection Agreement	2
Definitions	3
General Information	3
Lots and Grounds	4
Exterior Surface and Components	5
Outbuilding	6
Roof	6
Garage/Carport	7
Electrical	7
Structure	8
Attic	8
Basement	9
Crawl Space	9
Air Conditioning	10
Fireplace/Wood Stove	10
Heating System	11
Plumbing	11
Bathroom	12
Kitchen	13
Bedroom	13
Living Space	14
Laundry Room/Area	14
Summary	15

Inspection Agreement

Inspector Name: Adam Singer
Company Name: Your Company Name Here
Address: 123 Somewhere Street
City State Zip: Anywhere, US 12345

This agreement and subsequent report is for the property inspected at 1234 School House Road, Yourtown, US 12345 on 9/30/12.

Here is the main body of the agreement with this text repeated over and over. The agreement can be as long or as short as you want it to be. It is very easy to take the text that you have in another document and copy/paste it into Palm-Tech.

Here is the main body of the agreement with this text repeated over and over. The agreement can be as long or as short as you want it to be. It is very easy to take the text that you have in another document and copy/paste it into Palm-Tech. Here is the main body of the agreement with this text repeated over and over. The agreement can be as long or as short as you want it to be. It is very easy to take the text that you have in another document and copy/paste it into Palm-Tech.

Here is the main body of the agreement with this text repeated over and over. The agreement can be as long or as short as you want it to be. It is very easy to take the text that you have in another document and copy/paste it into Palm-Tech. Here is the main body of the agreement with this text repeated over and over. The agreement can be as long or as short as you want it to be. It is very easy to take the text that you have in another document and copy/paste it into Palm-Tech.

Here is the main body of the agreement with this text repeated over and over. The agreement can be as long or as short as you want it to be. It is very easy to take the text that you have in another document and copy/paste it into Palm-Tech.

Sign below to indicate that you accept the terms of this agreement.

Client: Bob Smith

Signature: 

Inspection Date: 9/30/12

Definitions

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

A	Acceptable	Functional with no obvious signs of defect.
NP	Not Present	Item not present or not found.
NI	Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of inspection.
M	Marginal	Item is not fully functional and requires repair or servicing.
D	Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.

General Information

Property Information

Property Address 1234 School House Road
City Yourtown **State** US **Zip** 12345
Contact Name Ima Goodagent
Phone (111)-111-1111 **Fax** (111)-111-1111

Client Information

Client Name Bob Smith
Client Address 3212 Homestead Dr.
City Yourtown **State** US **Zip** 12345
Phone (111)-111-1234 **Fax** n/a
E-Mail buyer@usedhouse.com

Inspection Company

Inspector Name Adam Singer
Company Name Your Company Name Here
Address 123 Somewhere Street
City Anywhere **State** US **Zip** 12345
Phone (111)111-2111 **Fax** (111)111-2111
E-Mail inspections@inspector.com
Amount Received \$350.00

Conditions


Others Present Buyer's Agent and Buyer **Property Occupied** Occupied
Estimated Age 15 **Entrance Faces** Northwest
Inspection Date 9/30/12
Start Time 10:00am **End Time** 1:00pm
Electric On Yes No Not Applicable
Gas/Oil On Yes No Not Applicable
Water On Yes No Not Applicable
Temperature 70 degrees
Weather Partly cloudy **Soil Conditions** Dry
Building Type Single family **Garage** Detached
Sewage Disposal City **How Verified** Visual Inspection
Water Source City **How Verified** Visual Inspection
Additions/Modifications Upgraded electrical service
Permits Obtained Electrical **How Verified** Multiple Listing Service

Lots and Grounds


Note: Wood sidings should be a minimum of 6" above ground. Detection of the presence of concealed moisture, mold or wood decay present behind exterior finishes is beyond the scope of this inspection. Promote positive (+) drainage away from foundation and extend runoff from roofing and downspouts a minimum 10 ft from foundation.

ANPNI M D

1. **Walks:** Concrete
2. **Steps/Stoops:** Concrete
3. **Patio:** Pebble top
4. **Deck:** Treated wood: The deck has been built below acceptable building standards and is not safe in its current state. Recommend further evaluation and estimate to bring deck up to an acceptable building standard.
5. **Balcony:** Concrete
6. **Porch:** Concrete
7. **Vegetation:** Shrubs with some weeds
8. **Retaining Walls:** Railroad ties: The wall is showing signs of movement, but appears to be stable at this time. A qualified contractor is recommended to evaluate and estimate repairs to maintain the wall.



9. **Basement Stairwell:** Concrete
10. **Grading:** Moderate slope: The grade and landscaping materials are too high and extend above the window well at the Northeast rear of the home. Recommend that the grade be reduced or the metal window well soil retainer be replaced with a taller unit to keep the mulch and soil beds from washing into the well.



11. **Swale:** Adequate slope and depth for drainage
12. **Window Wells:** Drain present
13. **Bsmt. Stairwell Drain:** Surface drain
14. **Exterior Surface Drain:** Not present
15. **Driveway:** Concrete
16. **Fences:** Split rail
17. **Lawn Sprinklers:** Front and back yard

Exterior Surface and Components

A NPNI M D

Front Elevation Exterior Surface

1. **Type:** Brick veneer: Loose half brick at front door. Remove and tuckpoint back in place.



2nd Floor rear dormer Exterior Surface

2. **Type:** Vinyl siding
 3. **Trim:** Composite material: Note: Damaged wood areas should be checked while doing the repair and replaced if wood rot is present.

1. Water damage to trim wood at either side of garage door from moisture wicking into the finished particle board. The surface is starting to delaminate. Recommend repair/replacement of the trim boards and silicone seal wood that is in contact with concrete to prevent wicking.

2. The wood window boxes have water damage and will require repair/replacement. The wood has started to separate at the supports and at the corners of the window boxes.

3. The trim board at the southwest corner of the porch has water damage due to water penetration. The trim board extends out creating a ledge allowing water to collect on the top edge of the board and cause the wood to rot.



4. **Fascia:** Composite material
 5. **Soffits:** Composite material
 6. **Door Bell:** Hard wired
 7. **Entry Doors:** Metal
 8. **Patio Door:** Vinyl sliding
 9. **Windows:** Vinyl
 10. **Storm Windows:**
 11. **Window Screens:**
 12. **Basement Windows:** Aluminum slider
 13. **Exterior Lighting:** Surface mounted lamps front and rear
 14. **Exterior Electric Outlets:** 110 VAC GFCI
 15. **Hose Bibs:** Frost Free
 16. **Gas Meter:** Exterior surface mount at side of home
 17. **Main Gas Valve:** Located at main line

Outbuilding

A N P N I M D

East corner of lot Outbuilding

1. **Exterior Surface:** Vinyl siding
2. **Roof:** Fiberglass shingle
3. **Roof Structure:** Wood truss
4. **Ceiling:** Drywall
5. **Walls:** Drywall
6. **Floor:** Concrete
7. **Foundation:** Poured slab
8. **Doors:** Steel
9. **Windows:** Vinyl double hung
10. **Electrical:** 110 VAC outlets and lighting circuits
11. **Plumbing:** Copper
12. **HVAC Source:** Convection baseboard
13. **Gutters:** Aluminum
14. **Downspouts:** Aluminum
15. **Leader/Extension:** Missing


Roof

Chimney flue inspection is limited due to height. The inspection covers only the visible portion of the flue.

A N P N I M D

Main Roof Surface

1. **Method of Inspection:** On the roof
2. **Unable to Inspect:** 30%: Height of the roof
3. **Material:** Fiberglass shingle: **Missing roof shingles from wind damage as marked "x" in diagram. Repairs are required.**
4. **Type:** Gable



5. **Approx Age:** 7
6. **Flashing:** Aluminum
7. **Valleys:** Preformed metal
8. **Skylights:**
9. **Plumbing Vents:** PVC
10. **Electrical Mast:** Underground utilities
11. **Gutters:** Aluminum

Roof (Continued)

12. **Downspouts:** Aluminum
 13. **Leader/Extension:** Underground conductors: **Reconnect to downspout where pulling loose.**



Southeast Chimney


14. **Chimney:** Aluminum siding & frame covered 3 wall pipe
 15. **Flue/Flue Cap:** Metal
 16. **Chimney Flashing:** Aluminum

Garage/Carport

A NPNI M D

Left Elevation Garage

1. **Type of Structure:** Tuck under **Car Spaces:** 2
 2. **Garage Doors:** Insulated aluminum
 3. **Door Operation:** Mechanized
 4. **Door Opener:** Lift Master: **The door contact safety switch is out of adjustment and does not reverse the door operation when the door comes in contact with an object in its path.**
Recommend adjustment of door contact switch.
Note: The light beam safety is operative.
 5. **Service Doors:** Metal
 6. **Ceiling:** Drywall
 7. **Walls:** Drywall
 8. **Floor/Foundation:** Poured concrete: **Cracked with minor displacement**
 9. **Hose Bibs:** Frost Free
 10. **Electrical:** 110 VAC outlets and lighting circuits
 11. **Smoke Detector:** Hard wired with battery backup
 12. **Heating:** Air exchange ventilation
 13. **Windows:** Vinyl double hung



Electrical

Testing of smoke detectors or alarms, timers, low voltage circuits such as door bells, security, and pet containment systems are beyond the scope of this inspection. Smoke detectors are recommended to be located in each Bedroom and one per floor level. Smoke alarms should be tested monthly and replaced per manufacturers guidelines or every ten years. Recommend grounded and GFCI protected outlets be installed at all Exterior, Kitchen, Wet Bar, Garage and Unfinished Basement outlet locations.

A NPNI M D


1. **Service Size Amps:** 150 Volts: 110-240 VAC
 2. **Service:** Aluminum
 3. **120 VAC Branch Circuits:** Copper
 4. **240 VAC Branch Circuits:** Copper
 5. **Aluminum Wiring:** Not present
 6. **Conductor Type:** Romex
 7. **Ground:** Plumbing and rod in ground.

Electrical (Continued)

8. **Smoke Detectors:** Hard wired with battery backup: **Safety: Recommend replacing batteries every 6 months**

Basement Electric Panel

9. **Manufacturer:** General: **Double taps noted in panel at several breakers. Recommend corrections**



10. **Max Capacity:** 150 Amps

11. **Main Breaker Size:** 150 Amps
12. **Breakers:** CU/AL
13. **Fuses:** Not present
14. **AFCI** 110 volt
15. **GFCI** Basement, garage, kitchen, bathrooms
16. **Is the panel bonded?** Yes No

Structure

A NPNI M D


1. **Structure Type:** Wood frame
2. **Foundation:** Poured
3. **Differential Movement:** No movement or displacement noted
4. **Beams:** Steel I-Beam
5. **Bearing Walls:** Frame
6. **Joists/Trusses:** 2x10
7. **Piers/Posts:** Poured piers and steel posts
8. **Floor/Slab:** Poured slab
9. **Stairs/Handrails:** Wood stairs with metal handrails
10. **Subfloor:** Composite manufactured materials

Attic

A NPNI M D

Northeast Attic

1. **Method of Inspection:** In the attic
2. **Unable to Inspect:** 10%: Cathedral or vaulted ceiling
3. **Roof Framing:** 2x4 Truss
4. **Sheathing:** Strand board
5. **Ventilation:** Ridge and soffit vents
6. **Insulation:** Fiberglass: **Insufficient insulation present at roof line above front bedroom closet. Add additional insulation below the roof line at the front of the home near the access cover. There is a small section of fiberglass batt insulation present that should be inserted in the open void above the closet framing. Additional insulation should be added in the 3 to 4 foot section to prevent condensation from forming due to heat loss.**
7. **Insulation Depth:** 12"
8. **Vapor Barrier:** Plastic
9. **Attic Fan:** Direct drive



Attic (Continued)

- 10. **House Fan:** Direct drive with manual controls
- 11. **Wiring/Lighting:** 110 VAC lighting circuit
- 12. **Moisture Penetration:** Previous water penetration noted
- 13. **Bathroom Fan Venting:** Electric fan

Basement

A NPNI M D

Main Basement

- 1. **Unable to Inspect:** 20%: Storage boxes, Storage shelves
- 2. **Floor Drain:** Surface drain
- 3. **Doors:** Hollow wood
- 4. **Windows:** Vinyl slider
- 5. **Electrical:** 110 VAC GFCI
- 6. **HVAC Source:** Air exchange ventilation
- 7. **Insulation:** Fiberglass
- 8. **Ventilation:**
- 9. **Sump Pump:**
- 10. **Moisture Location:** None found
- 11. **Bsmt Stairs/Railings:** Wood stairs with metal handrails

Crawl Space

A NPNI M D

East Crawl Space

- 1. **Method of Inspection:** In the crawl space
- 2. **Unable to Inspect:** 40%: Insulation obstructed complete view of foundation walls
- 3. **Access:** Wood door
- 4. **Moisture Penetration:** Visible evidence: Owner disclosed previous moisture concerns- see seller's disclosure
- 5. **Moisture Location:** Wall crack-Previous leak
- 6. **Moisture Barrier:** Plastic under gravel
- 7. **Ventilation:** Open to basement: No ventilation to exterior present
- 8. **Insulation:** Fiberglass
- 9. **Vapor Barrier:** Plastic
- 10. **Sump Pump:** Submerged
- 11. **Electrical:** 110 VAC

Air Conditioning

Mechanical equipment tested for functional operation at time of inspection only. No life expectancy is expressed or implied. Inspection does not determine balancing or sizing of system. The inspection covers only the visible components of the air conditioning system. Hidden problems may exist that are not documented in this report. Annual cleaning and servicing recommended for best performance and life expectancy.

A N P N I M D

Main AC System

1. **A/C System Operation:** Appears serviceable
2. **Condensate Removal:** PVC
3. **Exterior Unit:** Left side
4. **Manufacturer:** Lennox
5. **Model Number:** AA1CJ030-A **Serial Number:** 3-509859083
6. **Area Served:** Whole building **Approximate Age:** 7
7. **Fuel Type:** 220 VAC **Temperature Differential:** 22*
8. **Type:** Central A/C **Capacity:** 2.5 Ton
9. **Visible Coil:** Copper core with aluminum fins: Coils require cleaning

10. **Refrigerant Lines:** Low pressure and high pressure
11. **Electrical Disconnect:** Breaker disconnect
12. **Exposed Ductwork:** Metal
13. **Blower Fan/Filters:** Direct drive with disposable filter
14. **Thermostats:** Programmable



Fireplace/Wood Stove

A N P N I M D

Family Room Fireplace

1. **Freestanding Stove:**
2. **Fireplace Construction:** Stone
3. **Type:** Wood burning
4. **Fireplace Insert:**
5. **Smoke Chamber:** Brick
6. **Flue:** Tile
7. **Damper:** Metal
8. **Hearth:** Raised


Heating System

Mechanical equipment tested for functional operation at time of inspection only. No life expectancy is expressed or implied. Inspection does not determine balancing or sizing of system. The inspection covers only the visible components of the heating system. Hidden problems may exist that are not documented in this report. Annual cleaning and servicing recommended for best performance and life expectancy.

A N P N I M D

Basement Heating System

1. **Heating System Operation:** Appears functional
2. **Manufacturer:** Lennox
3. **Model Number:** 23495-320945 **Serial Number:** 43p93=24985=30
4. **Type:** Forced air **Capacity:** 100,000 BTUHR
5. **Area Served:** Whole Bldg **Approximate Age:** 7
6. **Fuel Type:** Natural gas
7. **Heat Exchanger:** 5 Burner: Recommend inspection by a qualified heating specialist
8. **Unable to Inspect:** 40%
9. **Blower Fan/Filter:** Direct drive with disposable filter
10. **Distribution:** Metal duct
11. **Circulator:**
12. **Draft Control:** Automatic
13. **Flue Pipe:** Double wall
14. **Controls:** Limit switch
15. **Devices:**
16. **Humidifier:** April-Aire: Humidifier water panel has excessive buildup. Recommend cleaning periodically. See illustration for water panel location.



17. **Thermostats:** Programmable
18.
19. **Suspected Asbestos:** No

Plumbing

Water heater tested for functional operation at time of inspection only. No life expectancy is expressed or implied. Approx. 200 gallons of water was pushed through sewer drain lines to verify functional drainage of public sewer or septic system. Water conditioning/filtering systems are not within the scope of this inspection. Recommended water pressure ranges 55-65 psi.

A N P N I M D

1. **Service Line:** Copper
2. **Main Water Shutoff:** Basement
3. **Water Lines:** Copper
4. **Drain Pipes:** PVC
5. **Service Caps:** Accessible
6. **Vent Pipes:** PVC
7. **Gas Service Lines:** Cast iron

Basement Water Heater

8. **Water Heater Operation:** Appeared servicable at time of inspection
9. **Manufacturer:** State
10. **Model Number:** PRV50 NBRT0 **Serial Number:** J957470005
11. **Type:** Natural gas **Capacity:** 50 Gal.

Plumbing (Continued)

12. **Approximate Age:** 7 **Area Served:** Whole building

13. **Flue Pipe:** Single wall

14. **TPRV and Drain Tube:** Missing drain tube: **Missing drain tube**



Bathroom

Inspection does not cover any damage concealed by rugs, carpeting, wall paneling, furniture or fixtures. Typical wall/ceiling minor cracks/touch ups are considered normal and are not listed in report.

A N P N I M D

Master Bathroom Bathroom

1. **Closet:** Large

2. **Ceiling:** Drywall

3. **Walls:** Drywall

4. **Floor:** Carpet

5. **Doors:** Hollow wood

6. **Windows:** Vinyl double hung

7. **Electrical:** 110 VAC outlets and lighting circuits

8. **Counter/Cabinet:** Laminate and wood

9. **Sink/Basin:** Corian

10. **Faucets/Traps:** Moen fixtures with a PVC trap: **Leaking trap, repair required**



11. **Tub/Surround:** Fiberglass tub and ceramic tile surround

12. **Shower/Surround:** Fiberglass pan and ceramic tile surround

13. **Spa Tub/Surround:**

14. **Toilets:** 3 Gallon Tank

15. **HVAC Source:** Air exchange ventilation

16. **Ventilation:** Electric ventilation fan and window

Kitchen

Appliances are tested for functional operation at time of inspection only. No life expectancy is expressed or implied. Inspection does not cover any damage concealed by rugs, carpeting, wall paneling, furniture or fixtures. Typical wall/ceiling minor cracks/touch ups are considered normal and are not listed in report.

A N P N I M D

1st Floor Kitchen

1. **Cooking Appliances:** General Electric
2. **Ventilator:** Air Care
3. **Disposal:** In-Sinkerator
4. **Dishwasher:** General Electric: SAFETY ISSUE- Hotpoint Dishwashers from 4/83 to 1/89, Slide - switch fire hazard, GSD500D, with S/N with 2nd letter of A. Contact GE at 1-800-599-2929 or www.geappliancerecall.com for rebate info on replacement and/or supplemental rewiring option of existing unit.
5. **Air Gap Present?** Yes No Air gap hose improperly connected
6. **Trash Compactor:** In-Sinkerator
7. **Refrigerator:** Frigidaire: Loose or damaged door seal
8. **Microwave:** Amana
9. **Sink:** Porcelain
10. **Electrical:** 110 VAC GFCI
11. **Plumbing/Fixtures:** PVC: Hot/Cold water operation reversed
12. **Counter Tops:** Laminate
13. **Cabinets:** Laminate and composite materials
14. **Pantry:** Large
15. **Ceiling:** Drywall
16. **Walls:** Drywall
17. **Floor:** Linoleum: Cuts or minor damage in flooring- repair/replace as required
18. **Doors:** Hollow wood
19. **Windows:** Vinyl double hung: Hard operation-needs improvements for ease of operation
20. **HVAC Source:** Air exchange ventilation

Bedroom

Inspection does not cover any damage concealed by rugs, carpeting, wall paneling, furniture or fixtures. Typical wall/ceiling minor cracks/touch ups are considered normal and are not listed in report.

A N P N I M D

2nd Floor Bedroom

1. **Closet:** Walk In
2. **Ceiling:** Drywall
3. **Walls:** Drywall
4. **Floor:** Carpet
5. **Doors:** Hollow wood
6. **Windows:** Vinyl double hung
7. **Electrical:** 110 VAC outlets and lighting circuits
8. **HVAC Source:** Air exchange ventilation
9. **Smoke Detector:** Hard wired with battery back up

Living Space

Inspection does not cover any damage concealed by rugs, carpeting, wall paneling, furniture or fixtures. Typical wall/ceiling minor cracks/touch ups are considered normal and are not listed in report.

A N P N I M D

Family Room Living Space

1. **Closet:** None
2. **Ceiling:** Drywall
3. **Walls:** Drywall
4. **Floor:** Hardwood
5. **Doors:** Hollow wood
6. **Windows:** Vinyl double hung
7. **Electrical:** Outlets, lighting and ceiling fan
8. **HVAC Source:** Air exchange ventilation
9. **Smoke Detector:** Hard wired with battery back up

Laundry Room/Area

Inspection does not cover any damage concealed by rugs, carpeting, wall paneling, furniture or fixtures. Typical wall/ceiling minor cracks/touch ups are considered normal and are not listed in report.

A N P N I M D

1st Floor Laundry Room/Area

1. **Closet:** Single small
2. **Ceiling:** Drywall
3. **Walls:** Drywall
4. **Floors:** Ceramic tile
5. **Doors:** Hollow wood
6. **Windows:** Vinyl double hung
7. **Electrical:** 110 VAC/220 VAC
8. **Smoke Detector:** Air exchange ventilation
9. **HVAC Source:** Air exchange ventilation
10. **Laundry Tub:** PVC
11. **Laundry Tub Drain:** PVC
12. **Washer Hose Bib:** Multi-port: Washer hose worn/expanded and ready to burst, recommend hose replacement with burst-proof stainless steel braided hoses
13. **Washer and Dryer Electrical:** 110-240 VAC
14. **Dryer Vent:** Rigid metal
15. **Dryer Gas Line:** Insulflex
16. **Washer Drain:** Floor drain
17. **Floor Drain:** Surface drain



Marginal Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

Lots and Grounds

1. **Vegetation:** Shrubs with some weeds
2. **Retaining Walls:** Railroad ties: The wall is showing signs of movement, but appears to be stable at this time. A qualified contractor is recommended to evaluate and estimate repairs to maintain the wall.

Garage/Carport

3. **Left Elevation Garage Floor/Foundation:** Poured concrete: Cracked with minor displacement

Electrical

4. **Basement Electric Panel Manufacturer:** General: Double taps noted in panel at several breakers. Recommend corrections

Attic

5. **Northeast Attic Moisture Penetration:** Previous water penetration noted

Crawl Space

6. **East Crawl Space Moisture Penetration:** Visible evidence: Owner disclosed previous moisture concerns- see seller's disclosure
7. **East Crawl Space Ventilation:** Open to basement: No ventilation to exterior present

Air Conditioning

8. **Main AC System Visible Coil:** Copper core with aluminum fins: Coils require cleaning

Kitchen

9. **1st Floor Kitchen Refrigerator:** Frigidaire: Loose or damaged door seal
10. **1st Floor Kitchen Floor:** Linoleum: Cuts or minor damage in flooring- repair/replace as required
11. **1st Floor Kitchen Windows:** Vinyl double hung: Hard operation-needs improvements for ease of operation

Laundry Room/Area

12. **1st Floor Laundry Room/Area Washer Hose Bib:** Multi-port: Washer hose worn/expanded and ready to burst, recommend hose replacement with burst-proof stainless steel braided hoses

Defective Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

Lots and Grounds

1. **Deck:** Treated wood: The deck has been built below acceptable building standards and is not safe in its current state. Recommend further evaluation and estimate to bring deck up to an acceptable building standard.
2. **Grading:** Moderate slope: The grade and landscaping materials are too high and extend above the window well at the Northeast rear of the home. Recommend that the grade be reduced or the metal window well soil retainer be replaced with a taller unit to keep the mulch and soil beds from washing into the well.

Exterior Surface and Components

3. **Front Elevation Exterior Surface Type:** Brick veneer: Loose half brick at front door. Remove and tuckpoint back in place.
4. **Trim:** Composite material: Note: Damaged wood areas should be checked while doing the repair and replaced if wood rot is present.
 1. Water damage to trim wood at either side of garage door from moisture wicking into the finished particle board. The surface is starting to delaminate. Recommend repair/replacement of the trim boards and silicone seal wood that is in contact with concrete to prevent wicking.
 2. The wood window boxes have water damage and will require repair/replacement. The wood has started to separate at the supports and at the corners of the window boxes.
 3. The trim board at the southwest corner of the porch has water damage due to water penetration. The trim board extends out creating a ledge allowing water to collect on the top edge of the board and cause the wood to rot.

Roof

5. **Main Roof Surface Material:** Fiberglass shingle: Missing roof shingles from wind damage as marked "x" in diagram. Repairs are required.
6. **Leader/Extension:** Underground conductors: Reconnect to downspout where pulling loose.

Garage/Carport

7. **Left Elevation Garage Door Opener:** Lift Master: The door contact safety switch is out of adjustment and does not reverse the door operation when the door comes in contact with an object in its path. Recommend adjustment of door contact switch.
Note: The light beam safety is operative.

Attic

8. **Northeast Attic Insulation:** Fiberglass: Insufficient insulation present at roof line above front bedroom closet. Add additional insulation below the roof line at the front of the home near the access cover. There is a small section of fiberglass batt insulation present that should be inserted in the open void above the closet framing. Additional insulation should be added in the 3 to 4 foot section to prevent condensation from forming due to heat loss.

Plumbing

9. **Basement Water Heater TPRV and Drain Tube:** Missing drain tube: Missing drain tube

Bathroom

10. **Master Bathroom Bathroom Faucets/Traps:** Moen fixtures with a PVC trap: Leaking trap, repair required

Defective Summary (Continued)

Kitchen

11. **1st Floor Kitchen Dishwasher:** General Electric: SAFETY ISSUE- Hotpoint Dishwashers from 4/83 to 1/89, Slide - switch fire hazard, GSD500D, with S/N with 2nd letter of A. Contact GE at 1-800-599-2929 or www.geappliancerecall.com for rebate info on replacement and/or supplemental rewiring option of existing unit.
12. **1st Floor Kitchen Plumbing/Fixtures:** PVC: Hot/Cold water operation reversed